Art Unit: 2856

Response

Attorney Docket No.: 062373

REMARKS

Claims 1, 5-11, 13-18, 27-30, 35 and 36 are pending in the application. The Examiner is

requested to reconsider this application in view of the following remarks. It is respectfully

submitted that this Amendment is fully responsive to the Office Action dated February 8, 2008.

As to the Merits:

As to the merits of this case, the Examiner reapplies the Rynhart et al. reference (USP

6,340,892, hereinafter "Rynhart") and applies the newly cited reference of Skidmore et al. (US

Patent Application No. 2003/0040934, hereinafter "Skidmore") in setting forth the following

rejection:

claims 1, 5-11, 13-18, 27-30, 35 and 36 stand rejected under 35 U.S.C. §103(a) as being

unpatentable over Rynhart in view of Skidmore.

This rejection is respectfully traversed.

Independent claim 1 calls for measuring a plurality of moisture content levels within said

interior portion of the structure; determining if each of said plurality of moisture content levels

is within a desired level; and issuing a moisture level compliance certificate if the result of said

determining step is that each of said plurality of moisture content levels is below the desired

level; wherein said measuring step includes taking measurements of said moisture content levels

- 2 -

Attorney Docket No.: 062373

around at least one window frame and at least one door frame, and along at least one floor, at

least one wall and at least one ceiling, all of which are included within said interior portion of

said structure. Independent claim 11 includes similar features.

It is respectfully submitted that the Examiner's reinstatement of the Rynhart reference for

teaching the features of independent claims 1 and 11 as set forth in item 6, page 4, of the Action

is completely without merit. That is, it is respectfully submitted that in the Response filed on

February 13, 2007, Applicants successfully argued that Rynhart is simply not concerned with

taking measurements of moisture content levels around at least one of window frame and at least

one of door frame, and along at least one floor, at least one wall, and at least one ceiling, all of

which are included within the interior portion of the structure, determining if each of the plurality

of the moisture content levels is within a desired level; and issuing a moisture level compliance

certificate if it is determined that each of the plurality of measured moisture content levels is

below the desired level in order to certify that the interior portion of the structure is free from

mold, moisture and any damage thereof that may result from mold or moisture. In response to

Applicants' position provided in the Response filed on February 12, 2007, the Examiner

correctly withdrew his reliance of the Rynhart reference.

Now, the Examiner asserts in item 6, page 4 of the Action, that Rynhart discloses that

moisture content is determined with structural components of an interior of a structure, and

specifically relies on the disclosure in column 1, lines 25-26 and column 2, lines 65 through

- 3 -

Art Unit: 2856

Attorney Docket No.: 062373

column 3, line 2 of the reference. However, such disclosure of the Rynhart reference merely

indicates that it is a further object of the Rynhart reference to provide for more accurate

determination of moisture content, as noted in column 1, lines 25-26, and that a meter 1 is used

for measuring moisture in a range of materials including wood, drywall, plaster, brick, roofing

and in siding, as noted in column 2, lines 65 through column 3, line 2.

Moreover, while Rynhart may disclose using a meter 1 for measuring the moisture

content for a range of different materials, Rynhart fails to include any type of disclosure or

teaching regarding a measuring step which includes taking measurements for moisture content

levels around at least one window frame and at least one door frame, and along at least one floor,

at least one wall, and at least one ceiling, all of which are included within an interior portion of

the structure, determining if each of the plurality of moisture content levels are within the desired

level and issuing a moisture level compliance certificate if the result of the determining step is

that each of the plurality of moisture content levels is below the desired level.

The Examiner has failed to specifically rely on any portion of the Rynhart reference

which teaches the measuring step which includes taking measurements of the moisture content

levels around at least one window frame and at least one door frame, and along at least one floor,

at least one wall, and at least one ceiling, all of which are included within the interior portion of

said structure, and determining if each of said plurality of moisture content levels is within a

desired level.

- 4 -

Art Unit: 2856

Response

Attorney Docket No.: 062373

Accordingly, it is submitted Rynhart fails to disclose or fairly suggest the features of

claim 1 concerning measuring a plurality of moisture content levels within said interior portion

of the structure; determining if each of said plurality of moisture content levels is within a

desired level; and issuing a moisture level compliance certificate if the result of said determining

step is that each of said plurality of moisture content levels is below the desired level; wherein

said measuring step includes taking measurements of said moisture content levels around at

least one window frame and at least one door frame, and along at least one floor, at least one

wall and at least one ceiling, all of which are included within said interior portion of said

structure.

In addition, Applicants submit that the Examiner is practicing Piecemeal Examination of

the present application, as evidenced by the Examiner's withdrawal of the Rynhart reference in

view of Applicants' persuasive arguments provided in the February 12, 2007 response, and the

Examiner's reinstatement of the Rynhart reference without the Examiner providing any type of

detailed analysis of the reference with regard to the above-noted features of the claimed

invention, as noted above. In addition, Applicants also strongly notes that this is the sixth Office

Action issued by the Examiner in this application and the Examiner has failed to present any

references which teach the features of the present claimed invention as included in the

independent claims 1 and 11.

- 5 -

Art Unit: 2856 Attorney Docket No.: 062373

Response

With regard to the newly cited reference of Skidmore, it is respectfully submitted that such reference fails to cure the above-noted drawbacks and deficiencies of the Rynhart reference.

That is, while Skidmore may disclose that an inspection database 36 is incorporated in the computer readable medium 34, it is submitted that the inspection database 36 fails to include an inspection item that includes information concerning measuring a plurality of moisture content levels within said interior portion of the structure; determining if each of said plurality of moisture content levels is within a desired level; and issuing a moisture level compliance certificate if the result of said determining step is that each of said plurality of moisture content levels is below the desired level; wherein said measuring step includes taking measurements of said moisture content levels around at least one window frame and at least one door frame, and along at least one floor, at least one wall and at least one ceiling, all of which are included within said interior portion of said structure.

Instead, Skidmore discloses in part in paragraph [0020] the following:

Foundation inspection items 40G include information concerning the moisture penetration, wall material, girders, sub-floor, sump pumps for crawl spaces, ventilation, and insulation. ...

Interior inspection items 40L include information concerning the rooms within the house, the floors and walls, any alarms, the ceiling, and any stairs or doors.

However, while the foundation inspection item 40G may include information concerning the moisture penetration of the foundation, it is submitted that Skidmore fails to disclose measuring a plurality of moisture content levels within an interior portion of the foundation

Response

Art Unit: 2856 Attorney Docket No.: 062373

structure. Instead, it is submitted that a home inspector would merely perform a visual inspection

of the foundation to determine if there is penetration of ground moisture in the foundation.

Moreover, it is submitted that Skidmore clearly fails to disclose or fairly suggest that the

inspection of the foundation includes a measuring step that includes taking measurements of said

moisture content levels around at least one window frame and at least one door frame, and

along at least one floor, at least one wall and at least one ceiling, all of which are included

within said interior portion of said structure. That is, it is submitted the foundation inspection

items 40G simply does not include information concerning moisture content levels that are

measured around a window frame and a door frame, and along a wall and a ceiling.

Further, while the interior inspection items 40L may include information concerning the

rooms within the house, the floors and walls, any alarms, the ceiling, and any stairs or doors,

Skidmore fails to provide any teaching or suggestion concerning determining the existence of

moisture within the rooms of the house, the floors, walls and doors.

As such, it is submitted that Skidmore's silence with regard to moisture existence with

within the rooms of the house, the floors, walls and doors teaches away from one of ordinary

skill in art including a measuring step that includes taking measurements of said moisture content

levels around at least one window frame and at least one door frame, and along at least one

- 7 -

Art Unit: 2856

Attorney Docket No.: 062373

Response

floor, at least one wall and at least one ceiling, all of which are included within said interior

portion of said structure.

In view of the above, it is submitted that even if, assuming arguendo, Rynhart and

Skidmore can be combined in the manner suggested by the Examiner, such combination would

still fail to teach or fairly suggest the features of claim 1 regarding measuring a plurality of

moisture content levels within said interior portion of the structure; determining if each of said

plurality of moisture content levels is within a desired level; and issuing a moisture level

compliance certificate if the result of said determining step is that each of said plurality of

moisture content levels is below the desired level; wherein said measuring step includes taking

measurements of said moisture content levels around at least one window frame and at least one

door frame, and along at least one floor, at least one wall and at least one ceiling, all of which

are included within said interior portion of said structure.

In view of the aforementioned remarks, Applicants submit that the claims are in condition

for allowance. Applicants request such action at an early date.

If the Examiner believes that this application is not now in condition for allowance, the

Examiner is requested to contact Applicants' undersigned attorney to arrange for an interview to

expedite the disposition of this case.

-8-

Art Unit: 2856

Response

Attorney Docket No.: 062373

If this paper is not timely filed, Applicants respectfully petition for an appropriate extension of time. The fees for such an extension or any other fees that may be due with respect to this paper may be charged to Deposit Account No. 50-2866.

Respectfully submitted,

WESTERMAN, HATTORI, DANIELS & ADRIAN, LLP

Thomas E. Brown
Attorney for Applicants

Registration No. 44,450 Telephone: (202) 822-1100

Facsimile: (202) 822-1111

TEB/nrp